

Work Order ID 145300

Thursday, May 05, 2016 1:27:43 PM

145300

Page 1

Item ID: D205-706-013 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: Fuel Purge Canister
 Start Date: 5/20/2016 Start Qty: 1.00 ***1*** Cust Item ID:
 Required Date: 5/27/2016 Req'd Qty: 1.00 ***1*** Customer:
 Reference:

Approvals: Process Plan: MCJ Date: MAY 06 2016 Tooling: _____ Date: _____ Run Start ***NR1***
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
IIN-D412-706	B								MCJ 160512
100	Document Control	0.00							
100	DOCUMENT CONTROL								
DC	Memo	0.00							
Doc.Control -USB or Paperwork	Photocopy bluefile and create labels per PPP D205-706-013 CHG003								
110	Pick Kit	0.00							
110									
Packaging	Memo	0.00							
Packaging									
120	QC4- 100% Inspect kits for completeness	0.00							
120									
QC	Memo	0.03							
Quality Control									

DAS
6
9-89

DAS
28
9-89

MAY 16 2016

DAS
6
9-89

DAS
27
9-89

MAY 12 2016
DAS
28
9-89

MAY 15 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
								Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	

Root Cause				FAULT CATEGORY			
Environment ☐	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐
Design ☐	☐	Operator	☐	Bending	☐	Set-up	☐
Doc/Data ☐	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐
Equip/Tooling ☐	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐
Handling/Pre ☐	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐
Material ☐	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐
Internal Transport ☐	☐	Poor Information	☐	Crushing	☐	Countersink	☐
Tribal Knowledge ☐	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐
LOA ☐	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐
Substation ☐	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐
Past Expiry Date ☐	☐	Manufacturing Process	☐	OTHER : _____			
Misidentified ☐	☐	Past Due	☐				

Work Order ID 145300

Thursday, May 05, 2016 1:27:43 PM

145300

Page 2

Item ID: D205-706-013

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Fuel Purge Canister

Start Date: 5/20/2016 Start Qty: 1.00 ***1***

Cust Item ID:

Required Date: 5/27/2016 Req'd Qty: 1.00 ***1***

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130	Packaging	0.00					DAS 28		
130							9-89		MAY 16 2016
Packaging	Memo	0.00							
Packaging	Identify and pack for shipping as per PPPD205-706-013 Location : FG018								
140	QC21- Final Inspection - Work Order Release	0.00							
140									MAY 17 2016
QC	Memo	0.10							
Quality Control									

MWS

Em 16/05/16

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QS1042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐	OTHER : ☐			

Picklist Print

Thursday, May 05, 2016 1:27:46 PM

Page 1

Work Order ID: 145300

145300

Parent Item: D205-706-013

D205-706-013

Parent Item Name: Fuel Purge Canister

Start Date: 5/20/2016

Required Date: 5/27/2016

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev:E 04.12.03 Remove AN6289-6D; Change Qty of AN924-6D
KJ/JLM IPP Rev:F 10.05.10 as per
chg002 DD verified :EC IPP Rev:G 12.12.07 as per IIN revB
DD verified by:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2001-4		Manufactured	No			110	Each	4.0000	1	1			
D2001-4									**				
Valve Assembly 1/4 inch													
	DAS 28 9-89			<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				ST012a		4							
				142185		4							
D3262-041		Manufactured	No			110	Each	1.0000	1	1			
D3262-041									**				
Canister Assembly													
	DAS 28 9-89			<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				ST492		1							
				143821		1							
D3264-1		Manufactured	No			110	Each	4.0000	2	2			
D3264-1									**				
Bracket													
	DAS 28 9-89			<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				st493		4							
				143791		4							
D3297-1-0121		Manufactured	No			110	Each	5.0000	1	1			
D3297-1-0121									**				
Hose Assembly													
	DAS 28 9-89			<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				ST209		5							
				140748		3							
				144480		2							

DAS
27
9-89

DAS
27
9-89

DAS
27
9-89

MAY 14 2016
DAS
27
9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

Picklist Print

Thursday, May 05, 2016 1:27:46 PM

Page 2

Work Order ID: 145300

145300

Parent Item: D205-706-013

D205-706-013

Parent Item Name: Fuel Purge Canister

Start Date: 5/20/2016

Required Date: 5/27/2016

Start Qty: 1.00

Required Qty: 1.00

D3297-1-0130

Manufactured No

110

Each

4.0000

1

1

DAS 6 27
9-89 9-89

D3297-1-0130

Hose Ass'Y

DAS
28
9-89

Location

Loc Qty

Loc Code

ST209

4

142183

2

144481

2

D3297-3-0350

Manufactured No

110

Each

3.0000

1

1

DAS 6 27
9-89 9-89

D3297-3-0350

Hose Assembly

DAS
28
9-89

Location

Loc Qty

Loc Code

ST209

3

142184

1

144149

2

D3298-001

Manufactured No

110

Each

5.0000

1

1

DAS 6 27
9-89 9-89

D3298-001

Tube Assembly

DAS
28
9-89

Location

Loc Qty

Loc Code

ST210

5

143824

5

D3298-009

Manufactured No

110

Each

3.0000

1

1

DAS 6 27
9-89 9-89

D3298-009

Tube Assembly

DAS
28
9-89

Location

Loc Qty

Loc Code

ST210

3

144995

3

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
				Completed By 					
				Lead hand / Supervisor Approval Verification 					
				QC / QA Coordinator Approval 					

Root Cause				FAULT CATEGORY							
Environment	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong	☐
Design	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions	☐
Doc/Data	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance	☐
Equip/Tooling	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect	☐
Handling/Pre	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing	☐
Material	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved	☐
Internal Transport	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing	☐
Tribal Knowledge	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish	☐
LOA	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread	☐
Substation	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence	☐
Past Expiry Date	☐	Manufacturing Process	☐	OTHER : _____							
Misidentified	☐	Past Due	☐								

Picklist Print

Thursday, May 05, 2016 1:27:46 PM

Page 3

Work Order ID: 145300

145300

Parent Item: D205-706-013

D205-706-013

Parent Item Name: Fuel Purge Canister

Start Date: 5/20/2016

Required Date: 5/27/2016

Start Qty: 1.00

Required Qty: 1.00

D3299-1

Manufactured No

110

Each

1.0000

1

1

D3299-1

Fitting

DAS
28
9-89

Location

Loc Qty

Loc Code

ST030

1

103865

1

**

DAS
6
9-89

DAS
27
9-89

D3299-3

Manufactured No

110

Each

7.0000

1

1

D3299-3

Fitting

DAS
28
9-89

Location

Loc Qty

Loc Code

ST030

7

103866

7

**

DAS
6
9-89

DAS
27
9-89

D3301-1

Manufactured No

110

Each

4.0000

1

1

D3301-1

Placard

DAS
28
9-89

Location

Loc Qty

Loc Code

ST030

4

144161

4

**

DAS
6
9-89

DAS
27
9-89

D3301-3

Manufactured No

110

Each

5.0000

1

1

D3301-3

Placard

DAS
28
9-89

Location

Loc Qty

Loc Code

ST030

5

144162

5

**

DAS
6
9-89

DAS
27
9-89

D3302-1

Manufactured No

110

Each

10.0000

1

1

D3302-1

Doubler

DAS
28
9-89

Location

Loc Qty

Loc Code

ST494

10

137783

10

**

DAS
6
9-89

DAS
27
9-89

MAY 11 2016

Thursday, May 05, 2016 1:27:46 PM

Shop Packet Print

Page 3

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

Picklist Print

Thursday, May 05, 2016 1:27:46 PM

Page 4

Work Order ID: 145300

145300

Parent Item: D205-706-013

D205-706-013

Parent Item Name: Fuel Purge Canister

Start Date: 5/20/2016

Required Date: 5/27/2016

Start Qty: 1.00

Required Qty: 1.00

D3302-3 Manufactured No

110 Each 9.0000 1 1

D3302-3

Doubler

DAS
28
9-89

Location

Loc Qty

Loc Code

ST494

9

140808

9

AN3-5A Purchased No

110 Each 318.0000 4 4

AN3-5A

Bolt

DAS
28
9-89

Location

Loc Qty

Loc Code

FP001

26

m133686

2

m134055

24

ST350

292

m134502

292

AN814-6D Purchased No

110 Each 3.0000 1 1

AN814-6D

Plug

DAS
28
9-89

Location

Loc Qty

Loc Code

ST326

3

m134405

3

AN815-6D Purchased No

110 Each 23.0000 2 2

AN815-6D

Union-M-Flare

DAS
28
9-89

Location

Loc Qty

Loc Code

CCK007

10

m134509

10

ST326

13

m132680

13

MAY 14 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

Picklist Print

Thursday, May 05, 2016 1:27:46 PM

Page 5

Work Order ID: 145300

145300

Parent Item: D205-706-013

D205-706-013

Parent Item Name: Fuel Purge Canister

Start Date: 5/20/2016

Required Date: 5/27/2016

Start Qty: 1.00

Required Qty: 1.00

AN833-6D

Purchased

No

110

Each

11.0000

3

3

AN833-6D

Elbow, Bulkhead-M-Flare

**

DAS
6 27
9-89 9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST324

11

M130466

11

3

AN924-6D

Purchased

No

110

Each

29.0000

4

4

AN924-6D

Nut

**

DAS
6 27
9-89 9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST322

29

m133938

5

m134502

24

4

NAS1149D0332J

Purchased

No

110

Each

1,116.000

4

4

NAS1149D0332.J

Washer

**

DAS
6 27
9-89 9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

CA

6

m129682

6

FP001

26

m133988

26

GA

60

m132677

60

ST260a

1000

m134502

1000

ST264

24

m133988

24

Thursday, May 05, 2016 1:27:46 PM

Shop Packet Print

Page 5

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

Picklist Print

Thursday, May 05, 2016 1:27:46 PM

Page 6

Work Order ID: 145300

145300

Parent Item: D205-706-013

D205-706-013

Parent Item Name: Fuel Purge Canister

Start Date: 5/20/2016

Required Date: 5/27/2016

Start Qty: 1.00

Required Qty: 1.00

NAS1149D0363J

Purchased

No

110

Each

2,248.000

8

8

NAS1149D0363.I

Washer

**

134562

DAS
27
9-89

Location

Loc Qty

Loc Code

GA

518

m134055

518

ST260a

1000

m134676

1000

ST263

730

m134606

730

8
2

DAS
28
9-89

NAS1149D0963J

Purchased

No

110

Each

50.0000

2

2

NAS1149D0963.I

Washer

**

DAS
27
9-89

Location

Loc Qty

Loc Code

ST263

50

125445

50

2

DAS
28
9-89

MS21042L3

Purchased

No

110

Each

1,726.000

4

4

MS21042I 3

Nut

**

DAS
27
9-89

Location

Loc Qty

Loc Code

FP001

100

m133790

100

GA

701

m133790

3

m134360

698

ST303

925

m134039

12

m134360

313

m134634

600

4

DAS
28
9-89

Thursday, May 05, 2016 1:27:46 PM

Shop Packet Print

Page 6

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QS1042) Approval 		
Description Work Order Deviation				Disposition					
								Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	

Root Cause			FAULT CATEGORY							
Environment ☐	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong
Design ☐	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions
Doc/Data ☐	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance
Equip/Tooling ☐	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect
Handling/Pre ☐	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing
Material ☐	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved
Internal Transport ☐	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing
Tribal Knowledge ☐	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish
LOA ☐	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread
Substation ☐	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence
Past Expiry Date ☐	☐	Manufacturing Process	OTHER : _____							
Misidentified ☐	☐	Past Due								

Picklist Print

Thursday, May 05, 2016 1:27:46 PM

Page 7

Work Order ID: 145300

145300

Parent Item: D205-706-013

D205-706-013

Parent Item Name: Fuel Purge Canister

Start Date: 5/20/2016

Required Date: 5/27/2016

Start Qty: 1.00

Required Qty: 1.00

MS21919-WDG12

Purchased

No

110

Each

34.0000

1

1

MS21919-WDG12

Clamp

**

DAS 6 27
9-89 9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST293

34

m129630

34

1

MS21919-WDG16

Purchased

No

110

Each

24.0000

2

2

MS21919-WDG16

Clamp

**

DAS 6 27
9-89 9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST292

24

m133363

4

m134676

20

2

MS21919-WDG9

Purchased

No

110

Each

145.0000

5

5

MS21919-WDG9

Clamp

**

DAS 6 27
9-89 9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST293

145

m134574

145

5

MS21920-42

Purchased

No

110

Each

9.0000

2

2

MS21920-42

CLAMP

**

DAS 6 27
9-89 9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST546

9

m134050

4

m134530

5

2

MAY 14 2016

DQA: _____ Date: _____

**WORK ORDER NON-CONFORMANCE / UPDATE**

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
								Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

Picklist Print

Thursday, May 05, 2016 1:27:46 PM

Page 8

Work Order ID: 145300

145300

Parent Item: D205-706-013

D205-706-013

Parent Item Name: Fuel Purge Canister

Start Date: 5/20/2016

Required Date: 5/27/2016

Start Qty: 1.00

Required Qty: 1.00

MS29512-06

Purchased

No

110

Each

34.0000

5

5

MS29512-06

O-RING

DAS 27
8 9-89

Location

Loc Qty

Loc Code

ST274

34

m132617

13

m132680

1

m134537

20

4
1

DAS
28
9-89

MS35489-11

Purchased

No

110

Each

14.0000

1

1

MS35489-11

GROMMET

DAS 27
8 9-89

Location

Loc Qty

Loc Code

ST269

14

m129499

14

1

DAS
28
9-89

DAS 8
MAY 9 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QS1042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐		OTHER : ☐					

DAS
28
9-89

5. PARTS LIST

Qty -011	Qty -013	Qty -015	Part Number	Description
X			D412-706-011	FUEL PURGE CANISTER INSTALLATION (212/412)
	X		D205-706-013	FUEL PURGE CANISTER INSTALLATION (205/214/EAGLE SINGLE)
		X	D204-706-015	FUEL PURGE CANISTER INSTALLATION (204)
1	1	1	D2001-4	VALVE ASSEMBLY
		2	D2026-101	SCREW
	1	1	D3262-041	CANISTER ASSEMBLY
1			D3262-043	CANISTER ASSEMBLY
2	2	2	D3264-1	BRACKET
1			D3297-1-0098	HOSE ASSEMBLY
1	1		D3297-1-0121	HOSE ASSEMBLY
	1		D3297-1-0130	HOSE ASSEMBLY
1			D3297-3-0210	HOSE ASSEMBLY
	1		D3297-3-0350	HOSE ASSEMBLY
		1	D3297-5-0410	HOSE ASSEMBLY
	1		D3298-001	TUBE ASSEMBLY
1			D3298-005	TUBE ASSEMBLY
1			D3298-007	TUBE ASSEMBLY
	1		D3298-009	TUBE ASSEMBLY
		1	D3298-011	TUBE ASSEMBLY
		1	D3298-013	TUBE ASSEMBLY
		1	D3298-015	TUBE ASSEMBLY
	1	1	D3299-1	FITTING
1	1		D3299-3	FITTING
1			D3299-5	FITTING
1			D3299-7	FITTING
1	1	1	D3301-1	PLACARD
1	1	1	D3301-3	PLACARD
1	1		D3302-1	DOUBLER
1	1		D3302-3	DOUBLER
		1	D3302-5	DOUBLER
		2	D3302-7	DOUBLER
2			D3329-1	BUSHING
1			D4054-001	TUBE ASSEMBLY
1			D4054-003	TUBE ASSEMBLY
1			D4054-009	TUBE ASSEMBLY
4	4	4	AN3-5A	BOLT
	1	1	AN814-6D	PLUG
1			AN814-8D	PLUG
2	2	2	AN815-6D	UNION
1			AN815-8D	UNION
		1	AN816-6D	NIPPLE
2	3	1	AN833-6D	ELBOW

• COPYRIGHT © 2004 BY DART AEROSPACE LTD. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: B

Date: 12.11.06